

**MSE 214 (Metals)**  
**Exercise 9 – Phase Diagrams II**  
**3<sup>rd</sup> December 2025**

**Question 1.**

The kinetics of the austenite to pearlite transformation obey the Avrami relationship. Using the table given below, determine the total time required for 95% of the austenite to transform to pearlite:

<b>Fraction transformed</b>	<b>Time (s)</b>
0.2	280
0.6	425

### Question 2.

In terms of thermal processing and the development of microstructure, what are the two major limitations of phase diagrams?


### Question 3.

The isothermal transformation diagram for a 1.13 wt% C steel alloy is shown below. Determine the final microstructure (in terms of just the microconstituents present) of a small specimen that has been subjected to the following time–temperature treatments.

In each case assume that the specimen begins at 920°C and that it has been held at this temperature long enough to have achieved a complete and homogeneous austenitic structure.

Recap: Red lines are reaction starts, green lines are reaction ends.

Recap 2: Only A can transform into the other solid phases (P, B, and M)




a) Rapidly cool to 775°C, hold for 500s, then quench to room temperature

- b) Rapidly cool to 625°C, hold for 1s, then quench to room temperature

**Question 4.**

Impact tests were carried out for aluminum and carbon steel over a variety of temperatures (in °C). The results are shown below. For the purposes of this question, you can think of the impact energy here as the area under the stress-strain curve. It represents the energy absorbed by the metal before failing.



- a) Based on these data, determine the crystal structures of the two materials. Explain your rationale.
- b) Suggest which metal would be best as a shock absorber operating at 200°C. Explain your rationale.
- c) Suggest which metal would be best as a “break-before-bend” bar at 50°C. Explain your rationale.

**Question 5.**

Give two reasons why martensite is so hard and brittle.

**Question 6.**

Welding is a process that involves joining two sections of a given metal by heating both sections to their melting point.

Improper welding of two steel plates often result in a higher brittle interface.

a) Why do you think this happens? Hint: What is the thermal conductivity of metals?

b) Suggest two ways we can modify the welding procedure to obtain steel plates without the brittle interface.