

# EE-365 - W4 INDUCTOR DESIGN FEW EXTRAS

**Prof. D. Dujic**

École Polytechnique Fédérale de Lausanne  
Power Electronics Laboratory  
Switzerland



## Typical catalog parts

Few variable parameters – same spec – sub-optimal design is acceptable – many customers



Figure 1 Power systems: distribution transformer



Figure 2 EMI filters: common mode chokes




Figure 3 Low power SMPS: SMD inductors

## Custom inductive components

- ▶ niche applications: railway, medicine, aerospace, research (e.g. CERN)...
- ▶ highly optimized converters: efficient PV inverters, cheap mass products,...
- ▶ power electronic converters: plethora of topologies × myriad of parameters

# CORE ASSEMBLY SET: CORE HALVES, COIL FORMER, YOKES ... WIRE AND AN AIR GAP



## Results to deliver: Inductor specification

Electrical specification	Core specification	Winding specification	Losses and diagrams
<ul style="list-style-type: none"><li>nominal inductance <math>L_{\text{nom}}</math></li><li>peak current <math>I_{\text{pk}}</math></li><li>current ripple <math>\Delta I_{\text{pkpk}}</math></li><li>ripple frequency <math>f_{\text{sw}}</math></li></ul>	<ul style="list-style-type: none"><li>core shape and size</li><li>core material</li><li>air gap length <math>l_g</math></li></ul>	<ul style="list-style-type: none"><li>wire diameter</li><li>number of turns</li></ul>	<ul style="list-style-type: none"><li>core and winding losses</li><li><math>LCR</math> meter results</li><li><math>L(I)</math> diagram</li><li>Thermal image for nominal dc current</li></ul>


## Discrete component values, multiobjective optimization → an iterative process

- Find a prospective core size
- Find wire diameters
- Tune the inductance by setting the air gap
- Verify the design parameters
- Iterate to fit the design values into the limits / to improve the design

$\left. \begin{array}{l} \text{1. Find a prospective core size} \\ \text{2. Find wire diameters} \\ \text{3. Tune the inductance by setting the air gap} \\ \text{4. Verify the design parameters} \end{array} \right\} \text{Calculations}$

$\left. \text{5. Iterate to fit the design values into the limits / to improve the design} \right\} \text{Experiment}$

# E CORE AND COIL FORMER. QUICK REVIEW OF SOME NOTIONS



- ferrite core
- bare copper wire
- coil former
- copper wire insulation
- $A_c$ : core c-s area
- $MLT$ : mean length per turn
- $l_g$ : air gap length
- $MPL$ : magnetic path length
- $W_A$ : core window area
- $W_{A,eff}$ : usable window area

Number of turns

$N_1, N_2, N_3$

Area of a bare copper wire

$A_{w1}, A_{w2}, A_{w3}$

Conductor area

$\sum_{x=1}^3 N_x \cdot A_{wx} = \blacksquare$

Wire area

$\blacksquare + \blacksquare$

Window utilization factor

$$K_u = \sum_{x=1}^3 N_x \cdot A_{wx} / W_A = \blacksquare / \blacksquare$$

Area product

$$A_p = W_A \times A_c = \blacksquare \times \blacksquare \text{ or } W_{A,eff} \times A_c = \blacksquare \times \blacksquare$$

Core geometry constant

$$K_g = W_A \cdot (A_c^2) / MLT = \blacksquare \times \blacksquare \times \blacksquare / \blacksquare \text{ or } \blacksquare \times \blacksquare \times \blacksquare \times \blacksquare / \blacksquare$$

Some notions vary: understand what you calculate!

# AREA PRODUCT - $A_p$ (INDUCTOR CASE)

## Two constraints:

- Core window area should fit the winding

$$W_{A_i} = \frac{N_i \cdot A_{wi}}{K_u} \geq \frac{N_i \cdot I_{rms_i}}{J_w \cdot K_u}$$

$$W_A \geq \frac{N_1}{K_u \cdot J_w} \sum_{i=1}^3 \frac{N_i}{N_1} I_{rms_i}$$

- Core should not saturate

$$A_c \geq \frac{\Psi_{max}}{N_1 \cdot B_{max}} = \frac{L \cdot I_{peak_1}}{N_1 \cdot B_{max}}$$

## Recall:

- Flux linkage  $\Psi$

$$\Psi = N \cdot \Phi = \int v_L dt = L \cdot I$$


## Merged Constraints

- Very approximate assumption for quick core search:
- Area Product  $A_p$  ( $[A_p] = m^4$ )

$$A_p = W_A A_c \geq \frac{L \cdot I_{peak_1} \sum_{i=1}^3 \frac{N_i}{N_1} I_{rms_i}}{K_u \cdot B_{max} \cdot J_w}$$

- LHS: core geometry related parameters:  $A_c$ ,  $W_A$  ( $W_{A,eff}$  if a coil former is used)
- RHS: design specifications:  $I_{max}$ ,  $I_{rms}$ ,  $L$ ,  $B_{max}$ ,  $K_u$ ,  $J_w$
- Degrees of freedom:  $N$ ,  $l_g$

## Inductor Geometry



## Limits for $N$

- lower limit: higher core losses, upper limit: higher copper losses

$$\frac{\Psi_{max}}{B_{max} \cdot A_c} < N_1 < \frac{W_A \cdot K_u \cdot J_w - \sum_{i=2}^3 N_i I_{rms_i}}{I_{rms_1}}$$

## Setting the $L$ value: by adjusting the gap length $l_g$

- recall:

$$L = \frac{N_1^2}{R_{c_e} + R_{g_e}} \approx \frac{N_1^2}{R_{g_e}} = \frac{\mu_0 A_c N_1^2}{l_g}$$

# FRINGING FLUX FACTOR

## Fringing flux

- ▶ Magnetic flux is forced to flow through the air gap, whereby  $Re_g \gg Re_c$
- ▶ Magnetic flux spreads out into the volume around the gap
- ▶ Result: lower air gap reluctance
- ▶ Consequently higher inductance than with flux through the air gap cross-section area only
- ▶ Fringing flux factor  $F_{\text{fringe}}$  (unitless) describes this increase of inductance ( $G$ : length of the core window):


$$F_{\text{fringe}} = 1 + \frac{l_g}{\sqrt{A_c}} \cdot \ln\left(\frac{2 \cdot G}{l_g}\right)$$

## Increased copper losses


- ▶ fringing flux induces eddy currents in conductive materials placed in its volume
- ▶ same principle as inductive heating
- ▶ significant additional power losses  $\rightarrow$  hot spot!
- ▶ solutions: distance to the gap, number of gaps, distributed gap materials

Other copper loss factors to consider at high frequency (not covered by lecture and exercise): Skin effect and proximity effect

## Fringing flux at the air gap



## Fringing flux induced copper losses



# DESIGN STEPS AT ONE GLANCE - FROM PAST PROJECTS

1. Specification and constraints:  $L_{\min}, I_L, \Delta I_L, f_{sw}, B_{\max}, K_u, J_w, R_L$
2. Pre-selection of cores
  - 2.1 Calculate the peak current  $I_{pk}$
  - 2.2 Calculate the energy handling capability:  $L \cdot I_{pk}^2$
  - 2.3 Calculate the approximate air gap  $l_g$  to store this energy
3. Select one core to start with using the area product  $A_p$
4. Select a wire diameter
  - 4.1 Calculate  $I_{rms}$
  - 4.2 Calculate the required bare wire area for the  $J_w$  constraint
  - 4.3 Select a wire within 10 % range
5. Calculate the required air gap length  $l_g$  and adjust  $N$ 
  - 5.1 Calculate the number of possible turns  $N_{1,2,3\max}$
  - 5.2 Calculate the required air gap length  $l_g$
  - 5.3 Calculate the fringing flux factor  $F_{fringe}$
  - 5.4 Calculate the new number of turns  $N_{1,2,3}$  by inserting  $F_{fringe}$
6. Verify the design constraints
  - 6.1 Calculate the window utilization  $K_u$
  - 6.2 Calculate the winding resistance  $R_{L1,2,3}$  for a hot wire.
  - 6.3 Estimate the copper loss  $P_{Cu}$
  - 6.4 Calculate the ac and peak flux densities  $B_{ac}$  and  $B_{pk}$
  - 6.5 Estimate the core loss  $P_{Core}$
  - 6.6 Estimate the temperature rise  $\Delta T$
7. Build the inductor and tune its value
8. Verify the winding direction of all 3 windings
9. Verify the core saturation
10. Verify the temperature rise



## STEP 7: AIR GAP TUNING AND RLC METER MEASUREMENT



Figure 4 Tools and material available to set and trim the air gap length




Figure 5 After winding  $N_1$




Figure 6 After winding  $N_2$



Figure 7 After winding  $N_3$

1. Wind the primary  $N_1$  turns on the coil former, add a tape layer when done.
2. Wind the secondary  $N_2$  turns on the coil former, add a tape layer when done.
3. Wind the auxiliary  $N_3$  turns on the coil former.
4. Use the Kapton tape to create the air gap on the two sides of the core.
5. Clamp the inductance using the yoke.

## STEP 8: WINDING DIRECTION AND RLC MEASUREMENTS




Figure 8 Winding direction test

1. Set the frequency on the RLC to 10kHz
2. Mark the primary winding terminal connected to the high potential of the RLC
3. Measure the voltage across the secondary and auxiliary winding
4. If the voltage is in phase with the primary voltage, mark the positive terminal, otherwise mark the negative terminal




Figure 9 RLC measurements

1. Disconnect the oscilloscope
2. Measure primary inductance with open secondary and auxiliary windings
3. Measure primary inductance with shorted secondary and auxiliary windings
4. Repeat measurements using the Bode100

## STEP 9: CORE SATURATION LIMIT VERIFICATION WITH THE POWER CHOKE TESTER

The Hardware Setup for the choke test:

- ▶ Keep the secondary and auxiliary winding open
- ▶ Connect both the Force and Sense cable to the power choke meter and to the terminals of the primary inductance
- ▶ Once connected, cover with Plexiglas box and do not touch until the end of the measuring process

The Software settings for the choke test:

- ▶ The max current value corresponds to your maximum input current rounded up
- ▶ The measured voltage value corresponds to your maximum input voltage
- ▶ For the pulse time enter 10ms

Results:

- ▶ Provide both the secant and incremental inductance measurements and show that they don't saturate




Figure 10 Power choke tester

## STEP 10: TEMPERATURE RISE MEASUREMENT

Verify the dc losses and the temperature rise

1. Position the camera safely and focus at the inductor windings.
2. Provide primary and secondary windings with their respective rms currents.
3. Take a picture of the test-setup as well as two thermal images, one done prior to the test and one after 15 minutes of test.

Attention: beware of reflections and non-black surfaces.



Figure 11 Heat-run test setup

