





$$\begin{aligned}l_1 &= 22 \\l_2 &= 17 \\l_3 &= 21 \\l_4 &= 19 \\l_5 &= 21\end{aligned}$$

$$\bar{l} = 20$$




Q

ll





$Q_{\hat{v}\hat{v}}$




$Q_{\hat{\ell}\hat{\ell}}$

$$\begin{aligned} \ell_1 &= 21 \\ \ell_2 &= 23 \\ \ell_3 &= 17 \\ \ell_4 &= 24 \\ \ell_5 &= 20 \end{aligned}$$


$$\bar{\ell} = 21$$




$Q_{\ell\ell}$



$\hat{\sigma}_0$



$Q_{\hat{v}\hat{v}}$



$Q_{\hat{\ell}\hat{\ell}}$

$$l_1 = 22$$



$$l_2 = 23$$

$$l_3 = 21$$

$$l_4 = 24$$


$$l_5 = 20$$

$$\bar{l} = 20$$




Q


l



$\hat{\sigma}_0$



$Q_{\hat{v}\hat{v}}$



$Q_{\hat{l}\hat{l}}$

$$l_1 = 22$$



$$l_2 = 17$$

$$l_3 = 29$$



$$l_4 = 19$$

$$l_5 = 21$$


$$\bar{l} = 21,6$$



Q_{ll}





$Q_{\hat{v}\hat{v}}$



$Q_{\hat{l}\hat{l}}$

$$\begin{aligned}
 l_1 &= 22 \\
 l_2 &= 17 \\
 l_3 &= 29 \\
 l_4 &= 19 \\
 l_5 &= 21
 \end{aligned}$$

$$\bar{l} = 24.6$$



Q_{ll}

